



- Asbestos air sampling location
- Asbestos, TSP/metals sampling and ambient dust monitoring location
- Debris remains, awaiting disposal
- Awaiting asbestos abatement
- Building demolished
- Decontamination in progress
- Demolition in progress
- Former site railroad (removed)
- Site boundary

Basemap source: Esri



EAGLE ZINC OPERABLE UNIT 1
MONTGOMERY COUNTY, HILLSBORO, ILLINOIS

DEMOLITION PROGRESS TRACKING
March 04 2015

EPA REGION 5 RAC 2 | REVISION 0 | March 2015

